Sanitized Copy Approved for Release 2011/01/12: CIA-RDP78B04558A000100230044-8

OUT56370

T 0 P S E C R E T 052031Z		1965 AUG 5 2	20 422	
PRIORITY	5143	· •	6 AUG 1965	25X1
IDEALIST		COF	PIES RECEIVED	7
		. V	ivo. Offing	Act
ATTN	at eigh		File	25X1
		1	OS	
SUBJ EVALUATION OF DELTA III TEST MISSION			ADMIN	
		PHOTO- 3	SEC BR	
1. THE FIRST DELTA III CAMERA SYSTEM WAS USED ON PHOTO-			CSD	
GRAPHIC TEST FLIGHTS FLOWN ON 8 AND 9 JUNE 1965. THE INITIAL			IPD	
			PD	
THE CONCLUTED OF A TOTAL OF LEG EDAMEC HUICH HEDE DOCCECED			PSD	
FLIGHT CONSISTED OF A TOTAL OF 150 FRAMES WHICH WERE PROCESSED			PSD-ICB	
AT CHIPS	OF THIS MISSION WERE FORWA	PORD TO 45	5 110	<u>⊬</u> 25X1
AI	OF INIS MISSION WERE FORWA	Modeb 10	PID	
THE SECOND FLIGH	T CONTAINED 953 FORWARD FR	AMES AND	94.7	<u> 25X</u> 1
		Warua BB0W	DIAXX 4	
1265 AFT FRAMES WHICH WERE EXPOSED FROM ALTITUDES RANGING FROM			SPAD	
CO TO TO THOUGAND FEET AND	anough open well-cities o	F 300 TO A10	NSA-LO DIA-AP	
62 10 70 THOUSAND FEET AND	GROUND SPEED VELOCITIES O	r 390 10 410	DIA-AP	
KNOTS. A PITCH AND ROLL E	XERCISE WAS INCLUDED. THE	MATERIAL VAS		
PROCESSED AT				25 X 1
2. ORIGINAL NEGATIVE:				
A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.				

- ALTHOUGH SAND AND DUST STORMS PREVENTED THE READING OF RESOLUTION TARGETS IT HAS BEEN DETERMINED THAT THE GROUND RESOLUTION IS BE-TWEEN 12 TO 15 INCHES. INDIVIDUALS CAN BE DISTINGUISHED AND COUNTED IN THE BOULDER DAM AREA.
- B. FWD LOOKING CAMERA: THE FIRST 17 FRAMES WERE FOGGED SUCH AS TO INDICATE A LIGHT LEAK IN THE FILM SUPPLY AREA OF THE VEHICLE. THE FILM WAS FOGGED WHILE SPOOLED AND EACH CONSECUTIVE FOGGED AREA IS SMALLER AND LESS AFFECTED.

TOP SEARCE

Explication and the second sec

- C. AFT LOOKING CAMERA: THE FIRST FRAME IS FOGGED. A MINUS DENSITY STREAK IS PRESENT Ø.5" FROM THE DIGITOTE EDGE OF THE FORMAT THROUGHOUT.
- D. BOTH CAMERAS: THERE ARE NO TIMING MARKS, CAMERA NUMBER OR BINARY WORD. TRANSVERSE BANDING IS PRESENT IN THE FIRST 0.5" OF ALL FORMATS AND DETECTABLE ACROSS THE ENTIRE FORMAT IN APPROXIMATELY 10 PERCENT OF THE MISSION. RAIL SCRATCHES ARE CONTINUOUS THROUGHOUT THE MISSION.

3. POSITIVES:

THE POSITIVES WERE NOT EVALUATED.

4. REMARKS: THE IMAGE QUALITY WAS NOT NOTICEABLY AFFECTED
BY THE PITCH AND ROLL EXERCISE. GOOD CULTURAL FEATURES WERE NOT
INCLUDED DURING THIS EXERCISE. THE EXPOSURES WERE OVER A
MOUNTAINOUS AREA AND ALTHOUGH SMEARS COULD NOT BE DETECTED IT
IS SUGGESTED THAT ADDITIONAL TESTS BE CONDUCTED OVER A MORE
CULTURAL AREA AND THAT THE RATE OF PITCH AND ROLL BE VARIED AND
RECORDED. ACTUAL PITCH AND ROLL SHOULD AFFECT ONLY THE GROUND
TRACK AND GROUND COVERAGE. THE RATE WILL AFFECT THE IMAGE
QUALITY.

TOPSECRET

-END OF MESSAGE-